·	Туре	L #	Hits	Search Text	DBs	Stamp		Error Definition	E r r
1	BRS	<b>L1</b>	384	(205/80 or 205/122 or 205/123 or 205/125 or 205/148 or 205/241 or 205/244 or 205/253 or 205/255 or 205/263 or 205/266 or 205/271 or 205/291 or 205/300 or 205/30	USP AT; US- PGP UB; EPO; JPO; DER WEN T; IBM	2004/04 /06 16:26			0
2	BRS	L2	799	1 and (electroplating or electroplated or electroplate or electrolytic or electrolysis or electrolytically) and tin	USP AT; US- PGP UB; EPO; JPO; DER WEN	2004/04 /06 16:27			
3	BRS	L3		2 and pyrone	USP AT; US- PGP UB; EPO ; JPO ; DER WEN	2004/04 /06 16:29			0
4	BRS	L4	1	1 and pyrone	USP AT; US- PGP UB; EPO; JPO; DER WEN	2004/04 /06 16:30			0

	σ	1	Document ID	Issue Date	Pag es	Title	Current OR	Current XRef
1			US 6706418 B2	2004031	6	Metal alloy compositions and plating methods related thereto	428/647	205/123; 205/125; 205/241; 205/253; 205/302; 205/304; 205/80; 428/457; 428/646; 428/935; 504/291

	Retriev al Classif	Inventor		s	С	P	2	3	4	5	Image Displ		PT
1		Egli, Ar al.	ndre et								US 670 <sup>°</sup> 6	418	